

2003-11

Final Report

Saw and Seal Repair Chisholm / Hibbing Airport Taxiway



Research

Technical Report Documentation Page

1. Report No. MN/RC – 2003-11	2.	3. Recipients Accession No.	
4. Title and Subtitle SAW AND SEAL REPAIR CHISHOLM-HIBBING AIRPORT TAXIWAY		5. Report Date January 2003	
		6.	
7. Author(s) Gerard T. Geib, P.E.		8. Performing Organization Report No.	
9. Performing Organization Name and Address Minnesota Department of Transportation Office of Materials 1400 Gervais Avenue Maplewood, MN 55109		10. Project/Task/Work Unit No.	
		11. Contract (c) or Grant (G) No.	
12. Sponsoring Organization Name and Address Minnesota Department of Transportation Office of Investment Management Research Services Section 395 John Ireland Boulevard Mail Stop 330 St. Paul, Minnesota 55155		13. Type of Report and Period Covered Construction Report August 2001 Field Review January 2002	
		14. Sponsoring Agency Code	
15. Supplementary Notes			
16. Abstract (Limit: 200 words) <p>The Chisholm-Hibbing Municipal Airport completed taxiway repairs of deteriorated sawed and sealed joints on August 6-8, 2001. This report documents the construction procedures, techniques, and materials used. A field review of the project was completed on January 24, 2002. This report also documents the initial performance of the repairs.</p> <p>Transverse thermal cracking, followed by the deterioration of the hot mix asphalt at the crack, is a major problem in Minnesota. The pavement between the cracks is often in good condition. The area within one foot of the crack begins to strip and collapse inward/downward. It also can tent up in the winter due to freezing moisture in the crack area. Both situations require repair. Long-lasting, cost-effective repairs at the cracked areas are needed.</p> <p>The hot pour, transverse patch material is a newer material that is fast, economical and durable. This material has the potential to be widely used for transverse crack repair on airports and roads in the state of Minnesota. This report focuses on the hot pour transverse patch material.</p>			
17. Document Analysis/Descriptors saw and seal hot pour patch material thermal cracking PolyPatch transverse crack		18. Availability Statement No restrictions. Document available from: National Technical Information Services, Springfield, Virginia 22161	
19. Security Class (this report) Unclassified	20. Security Class (this page) Unclassified	21. No. of pages 21	22. Price

**SAW AND SEAL REPAIR
CHISHOLM-HIBBING
AIRPORT TAXIWAY**

Construction Report
Leveling Cupped Joints
August 6-8, 2001

Field Review
January 24, 2002

Prepared by:

Gerard T. Geib, P.E.
Minnesota Department of Transportation
Office of Materials

January 2003

Published by:

Minnesota Department of Transportation
Research Services, MS 330
395 John Ireland Boulevard
St. Paul, MN 55155

The content of this report reflects the views of the authors who are responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the views or policies of the Minnesota Department of Transportation at the time of publication. This report does not constitute a standard, specification or regulation.

The authors and the Minnesota Department of Transportation do not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to this report.

ACKNOWLEDGEMENTS

The author would like to acknowledge the help of several people and groups whose work was essential to the completion of this project:

Chisholm-Hibbing Airport Authority

Dave Danielson, Executive Director

Contractor: Bergman Companies, Inc

Jim Pearson, sales representative, and crew

Material: Crafcro Inc. Supplier: Brock White Companies

Arlan Burggraaf, sales representative

Mn/DOT employees

Chris Cochran, John Hippchen, Roger Olson, Tom Wood, Bill Zerfas, and

Sandy McCully

SPONSORS

Chisholm-Hibbing Airport Authority

Mn/DOT Office of Aeronautics

Mn/DOT Office of Materials

TABLE OF CONTENTS

Introduction.....	1
Taxiway Prior to Repairs	2
Joints 1-7, Routed Joints, Type 1 Material, 75-ft. Spacing.....	3
Joints 8-23, Routed Joints, Type 3 Material, 75-ft. Spacing.....	5
Joints 24-26, Thermo Patch Repairs	8
Joints 27-32, Routed Joints, Type 3 Material, 50-ft. Spacing.....	11
Joints 33-35, Skimmed Joints, Type 3 Material, 50-ft. Spacing.....	11
Joints 36-45, Joints Sealant Only, 50-ft. Spacing	13
Field Review January 24, 2002.....	14
 Appendix A Crack Repair Summary Table	 16
Appendix B Chisholm – Hibbing Municipal Airport	17

EXECUTIVE SUMMARY

The Chisholm-Hibbing Municipal Airport completed taxiway repairs, of deteriorated sawed and sealed joints on August 6-8, 2001. This report documents the construction procedures, techniques, and materials used. A field review was completed on January 24, 2002. This report also documents the initial performance of the repairs.

Transverse thermal cracking, followed by the deterioration of the hot mix asphalt at the crack is a major problem in Minnesota. The pavement between the cracks is often in good condition. The area within one foot of the crack begins to strip and collapse inward/downward. It also can tent up in the winter due to freezing moisture in the crack area. Both situations require repair. Long-lasting, cost-effective repairs at the cracked areas are needed.

The hot pour, transverse patch material is a newer material that is fast, economical and durable. This material has the potential to be widely used for transverse crack repair on airports and roads in the state of Minnesota. This report focuses on the hot pour transverse patch material.

INTRODUCTION

Chisholm-Hibbing Municipal Airport

The Chisholm-Hibbing Municipal Airport completed taxiway repairs of deteriorated sawed and sealed joints on August 6-8, 2001. This report documents the construction procedures, techniques, and materials used. A field review was completed on January 24, 2002. This report also documents the initial performance of the repairs.

Thermal Cracks

Transverse thermal cracking, followed by the deterioration of the hot mix asphalt at the crack is a major problem in Minnesota. The pavement between the cracks is often in good condition. The area within one foot of the crack begins to strip and collapse inward/downward. It also can tent up in the winter due to freezing moisture in the crack area. Both situations require repair. Cost-effective repairs at the cracked area do not exist.

Chisholm-Hibbing Municipal Airport Taxiway Construction

The Chisholm-Hibbing Municipal Airport constructed a taxiway parallel to runway 31 in 1992 (see Appendix B). The taxiway is 50-ft. wide with 20-ft. shoulders on each side. The taxiway is 8-in. of HMA, on 6-in. of aggregate base, on 12-in. of subbase, on 30-in. of subgrade. Longitudinal drains were installed at the bottom of the subgrade, under the taxiway-shoulder joint. The shoulders are 4-in. of HMA. The pavement was sawed full depth, routed, and sealed at 50-ft. and 75-ft. intervals. Ten joints were sealed with silicone and a hot pour asphalt sealant was used in the remaining joints.

Chisholm-Hibbing Municipal Airport Taxiway Joint Deterioration and Repair

Secondary cracking parallel to the sawed joints appeared in 1995. At this time the joints appeared to be well sealed. The cracking was only on the thinner shoulder sections.

Deterioration and cupping at the joints continued until the repairs were made.

Three techniques were used:

- Hot pour, transverse patch material (newer product)
 - two mix sizes: regular and fine
 - two mix products based on air temperature ranges, type 1 and 3
 - Cost - \$8.00 / ln. ft.
- Thermo-bond asphalt repair
 - Cost - \$10.00 / ln. ft.
- Clean and seal, leveling with a hot pour sealant
 - Cost - \$2.50 / ln. ft.

Research Potential

The hot pour, transverse patch material is a newer material that is fast, economical and durable. This material has the potential to be widely used for transverse crack repair on airports and roads in the state of Minnesota. This report focuses on the hot pour transverse patch material.

Taxiway Prior to Repairs



Photo 1. Taxiway section. The centerline of the taxiway is toward the bottom of the photo. The taxiway is 50-ft. wide.



Photo 2. Close up of joint. Severe cupping occurred across the entire joint. The coin is a quarter.



Photo 3. Shoulder section, 20-ft. wide. The shoulder sections were in worse condition than the taxiway.

The sealant often appeared to be performing well, yet deterioration was present. Traffic loading (ESAL's) would be very low for this pavement.

ROUTED JOINTS, TYPE 1 MATERIAL, 75-FT. SPACING

JOINTS TREATED	Joints 1-7 were repaired with Polypatch. <i>Note: joints 2-7 “leveled” with a joint sealant(see page 11), 2 or 3 days after placement of the PolyPatch.</i>
INSTALLATION TECHNIQUE	Routing was not over the crack, see the photos below. Joint 1 was routed ~ ¼” deep. <i>Joint 2 was not routed.</i> Joints 3-7 were routed ~ ¾ -1” deep. Routed joints were broomed, air blasted, heat lanced and filled. All joints were level filled.
PRODUCT	Crafco PolyPatch Type 1 (34281) designed for use in colder climates, tested for flexibility at -20° F.
DATE	Aug. 6, 2001
COMMENT	Repair work, author not present. Photos represent work completed. Type 1 has a lower adhesion property (15 psi vs. 25 psi) than type 3, but type 1 will resist cracking during cold weather better than type 3.



Photo 4. Typical routed joint. Fill from the shoulder toward the centerline. Recommended application temperature is 375-410° F.



Photo 5. Type 1 material used the larger size aggregate, (vs. the fine mix – type 3). The routed edge provides a better “edge” for the material to bond against.

ROUTED JOINTS, TYPE 3 MATERIAL, 75-FT. SPACING

JOINTS TREATED	Joints 8-23 were repaired with PolyPatch. <i>Note: joint 8 was “leveled” with the joint sealant, 2 or 3 days after placement of the PolyPatch.</i>
INSTALLATION TECHNIQUE	Joints 8-23 were routed ~ ¾ -1” deep. Routed joints were broomed, air blasted, heat lanced and filled. All joints were level filled.
PRODUCT	Crafco PolyPatch Fine Mix -Type 3 (34286) material designed for temperatures ranging from 120° F down to 20° F was being added to the existing Crafco PolyPatch Type 1 in the melter. The fine mix material is easier to feather out to the edge of the patch.
DATE	Aug. 7, 2001
COMMENT	Joint 8 was all Type 1 material. Joint 10 was about 2/3 Type 1 and 1/3 Type 3. As the material in the melter was used up, only the Fine Mix -Type 3 was used.



Photo 6. The material easily flowed into cracks and provides a smooth level surface across the joint.



Photo 7. This is the 12-in. wide rake. A 19-in. wide rake was also used.

Photo 8. Completed joint 8. A 12-in. wide patch. Due to the settling of material, joints 2-8 were skimmed leveled with the joint sealant.





Photo 9. This is joint 9. The 19-in. rake shows that the cupping at the joint was often greater than a foot wide. The router was run across the taxiway on each side of the joint. This provided a better “edge” for the patch material to adhere to.



Photo 10. Filling joint 9. This is type 1 material. It will perform better in colder weather than fine mix - type 3. Type 1 has a lower adhesion property than type 3 (15psi vs. 25psi). The routed edge should help the patch material bond to the taxiway. The type 1 also has a larger aggregate size than the fine mix - type 3. Therefore type 1 is better suited for the deeper patches.

Type 1 and type 3 material are both manufactured in a “regular” and fine fix product.

Buckets are not typically used to apply this material. The rubber boot type applicator shoot was lost during transport.

THERMO PATCH REPAIR

JOINTS TREATED	Joints 24-26. Only three joints used the thermo patch repair technique.
INSTALLATION TECHNIQUE	The pavement surface was heated to approximately 400° F. The surface was hand raked. New HMA was added (a Wisconsin mix: 5.5-6.0% AC and 3/8-in. aggregate, at about 250° F). The heated pavement and new HMA were mixed together and recompactd.
PRODUCT	Thermo patch with new fine mix HMA added.
DATE	Aug. 7, 2001
COMMENT	These joints were at 75-ft. spacing.



Photos 11 and 12. Raking the heated joint. Additional new fine HMA was added and mixed together with the existing material. The joint will reflect through the patch.



Photo 13. Joint 26, preparing the area for compaction.



Photos 14, 15, 16, and 17. Compact each edge first, than roll down the center of the patch.



Photo 18. The heating unit progressed across each joint. The sawed and sealed joint will reflect through this repair. The width of this repair is about 41-42 inches.

Due to the small quantities of repair types, it is difficult to estimate production rates for the different repair methods used on this project.

ROUTED OR SKIMMED JOINT, TYPE 3 MATERIAL, 50-FT. SPACING

JOINTS TREATED	Joints 27-32 Joint 26 to 27 is 75-ft. apart. Joint 27 to 28 is 50-ft. apart. Joints (27-45) are spaced 50-ft. apart.
INSTALLATION TECHNIQUE	These joints were <i>planned</i> to be routed (see page 12). Routed joints were broomed, air blasted, heat lanced and filled. All joints were level filled.
PRODUCT	Crafco PolyPatch Fine Mix - Type 3 (34281) designed for temperatures ranging from 120° F down to 20° F.
DATE	Aug. 7, 2001
COMMENT	Type 3 has the best adhesion properties, but may crack in the winter.

JOINTS TREATED	Joints 33-35
INSTALLATION TECHNIQUE	These three joints were not routed. All joints were level filled by skimming the material across the cupped joint.
PRODUCT	Crafco PolyPatch Fine Mix - Type 3 (34281) designed for temperatures ranging from 120° F down to 20° F.
DATE	Aug. 7, 2001
COMMENT	Type 3 has the best adhesion properties, but may crack in the winter. The fine mix is best for skimming the patches (without routed edges) and feathering to the edge of the patch.



Photo 19. Typical skim patch operation. Clean and dry.



Photo 20. The pavement surface temperatures during this repair work were up to 140° F by mid afternoon.

JOINT SEALANT ONLY, 50-FT. SPACING

JOINTS TREATED	Joints 36-45
INSTALLATION TECHNIQUE	These joints were skimmed leveled with crack filling material.
PRODUCT	Crafco Roadsaver 221 sealant.
DATE	Aug. 7, 2001
COMMENT	This sealant meets the specifications of ASTM 3405. The estimated amount of material was 2 lbs./ln.ft. No photos were taken during the initial construction.

Photo 21. Joint 42. Taken on 1/24/2002 during the field review. Three pennies are stacked under the ruler. The sealant was stretching and sagging, but did not break open.



FIELD REVIEW: JANUARY 24, 2002

General

Chris Cochran and Jerry Geib completed a field review on January 24, 2002. The reported air temperatures ranged from 5° F to 9° F.

Observations



Photo 22.

Joint 1 was cracked. This was the first joint repaired. This was the first time the contractor placed this material. The repair was not as smooth as other repairs. This joint was not covered with the crack sealant material.



Photo 23. Joint 8 did not appear to be cracked; however joints 2-8 were “skimmed leveled” with joint sealant, approximately two days after placement of the PolyPatch material. The joint sealant may have been masking a small crack in the patching material.

Joint 9 was 50% cracked. Joints 10-23 were 100% cracked. Joints 2-8, with the more flexible material, did not appear to be cracked. However, the joint sealant may have been masking the crack. All joints, at 75-ft. spacing, with the less flexible type 3 material were cracked.



Photo 24. Joint 24. The three joints repaired by the thermo patch method had cracked.



Photo 25. Joint 28.

Joints 28-32 (50-ft. spacing) were not cracked. All joints (10-23) with the same material at 75-ft. spacing were cracked.

Joint 27 was cracked. This joint has a 75-ft. spacing toward joint 26 and a 50-ft. spacing toward joint 28.

Also note that joints 33-35 were cracked, using the same material and the same joint spacing as joints 27-32. The only difference was that joints 27-32 were *planned* to be routed and joints 33-35 were just to be skimmed. Due to conflicting construction documents, it is not known for sure that joints 27-32 were routed.

Joint 42 is shown on page 10. All of the joints with the joint sealant were not cracked.

APPENDIX A

Joint number	Repair material	Joint spacing	Routed edges	Comments
1-7	Type 1	75-ft.	yes	Joint 1 is cracked, first repair. Joints 2-7 no cracks, covered with sealant.
8-23	Type 3	75-ft.	yes	Joint 8 no crack, covered with sealant. Joint 9 50% cracked, type 1 and 3 material. Joints 10-23 all cracked, type 3 material.
24-26	Thermo patch	75-ft.	n/a	All three joints, 100% cracked.
27-32	Type 3	50-ft.	maybe	Joint 27 cracked, 75-ft spacing on one side. Joints 28-32 no cracks.
33-35	Type 3	50-ft.	no	All cracked.
36-45	Sealant	50-ft.	no	No cracks.

APPENDIX B

